




V-Burst™

Set-up Instructions

Basic Assembly

- 1) Spread collapsed display out in all four directions - fabric graphic facing up
- 2) Connect opposing J-hooks around perimeter of display
- 3) Stand display up and connect remaining center J-hooks from behind
- 4) Install the Radiance lights in the bottom and then attach the unprinted backer (see other side for details)
- 5) Attach Velcro from front graphic onto the sides of the unprinted backer
- 6) To break down, repeat steps in reverse
Note: make sure all J-hooks are disengaged before collapsing display



Radiance Lighting Set-Up

1)




After frame is assembled, position light mounting brackets into place on the bottom frame quad scissors.

Note: the brackets are notched specifically to create a level platform for light placement and may need to be rotated to fit different frame systems.

2)

Place Radiance lights into the mounting brackets and connect the wires and power supply.

Note: certain frame sizes will have multiple power supplies.



Great Quality Meets Great Prices
Our new line-up of quick-ship products are here.